



Hella Gutmann Solutions A/S  
2619 Lillehammer  
TLF: +47 35 93 40 06  
Mail: support@hella-gutmann.no

# Hotline info

## Bil info

|            |                     |
|------------|---------------------|
| Bilmerke:  | Mercedes            |
| Model:     | Sprinter 906 315CDI |
| Årsmøll:   | 2007                |
| Km stand:  | 125.000             |
| Motorkode: | 646.986             |

## Bilteknisk problem

- Lyser i motorlampe
- Går periodisk i nødprogram, typisk ved driftsvarm motor 90°C

## Feilkoder

P2359 –Ladetrykksregulering , funktion feiler





Hella Gutmann Solutions A/S  
2619 Lillehammer  
TLF: +47 35 93 40 06  
Mail: support@hella-gutmann.no

# Hotline info



## Løsning

- Innsugningsmanifold utett mellom aluminium og plast del.

